

Detroit District P.O. Box 1027 Detroit, MI 48231-1027 (313) 226-6797 FAX - (313) 226-3519

## Notice to Navigation Interests

Notice No. L06-50 Date: 6 SEPTEMBER 2006

Waterway: LAKE HURON Location: MICHIGAN

**CELRE-OT-T** 


## CONDITION OF FEDERAL NAVIGATION CHANNEL CASEVILLE HARBOR

- 1. Surveys performed within the Federal navigation channel at Caseville Harbor, Michigan during August 2006, indicate shoaling as shown on the back of this sheet.
- 2. Mariners are urged to use extreme caution in the area.
- 3. All inquiries should be addressed to CELRE-OT-T and should refer to Notice to Navigation Interests No. L06-50. Internet address: <a href="http://www.lre.usace.army.mil">http://www.lre.usace.army.mil</a> Go to: Detroit Home Page, Who We Are, Operations Office Home Page.

WILLIAM J. LEADY Lieutenant Colonel, U.S. Army District Engineer

## Notice to the Postmaster:

It is requested that the above notice be conspicuously and continuously posted until November 30, 2006.



The information depicted on this map represents the results of surveys made on the date indicated and can only be considered as indicating the general conditions existing at that time.

Surveys taken: August 2006

Ocasevil.bmp

Shoals indicate least available depth below LWD

All depths and project depths are referred to Low Water Datum elevation 577.5 ft. above Mean Water Level, IGLD, 1985.

## CASEVILLE HARBOR, MICHIGAN

CONDITION OF CHANNEL

ISSUED: 6 September 2006

U.S. Army Engineer District, Detroit